



**Bluelight Software**

902 Redwood Drive  
Loveland, CO 80538

Phone: 970-461-8554

Fax: 970-461-8555

NFPA Member  
Permit #93989593  
www.bluelightsw.com

www.efinitymobile.com  
sales@bluelightsw.com  
support@bluelightsw.com

Versatile Data Collection, Dynamic Forms Building  
Providing software solutions to service industries for decades

**WEEKLY FIRE PUMP TEST**

10/30/2006 - 11/3/2006

**Customer Address:**

Bluelight Software, LLC  
902 Redwood Drive  
Loveland, CO 80538  
Phone: (970) 461-8554  
Fax: (970) 461-8555

**Site Address:**

Bluelight Software, LLC  
902 Redwood Drive  
Loveland, CO 80538  
Phone: (970) 461-8554  
Fax: (970) 461-8555

Customer #: 111  
Contract #: 38434  
Job Status: Archived  
Job Name: Weekly Pump Test Sample Report

Contact: Al Riggs  
Site #: 53  
Inspection Date: 2/12/2007

Date	Building / Fire Pump	Pump Run Start Time	Pump Run End Time	FTE Pump Run Duration	Suction Pressure PSI	Discharge Pressure PSI	Pump Start PSI	Run Set Time (Min.)	Front Bearing Temp.	Bearing Temp.	RPM at Full Churn	Jockey Start PSI
11/1/2006	Pump 2	09:27 AM	10:27 AM	60	78	77	85	7	452	225	7500	79
11/2/2006	Pump 1	10:20 AM	11:20 AM	60	71	77	72	5	325	325	5000	76

Average FTE Pump Run Duration - 60

Total FTE Pump Run Duration - 120

**Notes and Deficiencies**

Pump 2 front bearing temperature exceeds safe operating limits. Bearing should be replaced.

Building / Fire Pump - Pump 2

Q# 9 - Front bearing temperature - 452



---

Customer: Jim Beam

11/2/2006



---

Inspection Technician: Sam Adams

11/2/2006